


31 The diagram shows a simple a.c. generator.



What is connected to G and H so that alternating current can be provided to an external circuit?

- A** cell
- B** commutator
- C** slip rings
- D** soft iron core